

Material Safety Data Sheet

Tribolube-26N

May be used to comply with OSHA's Hazard Communication Standard.
29 CFR 1910. 1200 Standard must be consulted for specific requirements.

QUICK IDENTIFIER
Common Name: (used on Label and list)

SECTION 1- MANUFACTURER

Manufacturer's
Name

Aerospace Lubricants, Inc

Address

1600 Georgesville Road

City, State, and Zip

Columbus, Ohio 43228

Emergency
Telephone No.

614-878-3600

Other
Information
Calls

614-878-3600

Signature of Person
Responsible for Preparation

Stephen E. Gates
Stephen E. Gates

Date
Prepared

January 3, 2006
Rev. D

HEALTH	1
FLAMMABILITY	0
REACTIVITY	0
PERSONAL PROTECTION	B

SECTION 2- HAZARDOUS INGREDIENTS/IDENTITY

Hazardous Component(s) (chemical & common name(s))	OSHA PEL	ACGIH TLV	Other Exposure Limits	% (optional)	CAS NO.
--	-------------	--------------	--------------------------	-----------------	------------

No hazardous components were knowingly incorporated into this lubricant

SECTION 3 - PHYSICAL & CHEMICAL CHARACTERISTICS

Boiling Point	Above 500°F	Specific Gravity (H O=1)	1.30	Vapor Pressure (mm Hg)	Less than 5 mm
Solubility in Water	Negligible	Reactivity in Water	Negligible		
Appearance and Odor	Yellow grease, slight petroleum odor	Melting Point	Above 550°F		
	Vapor Density (Air=1)		N/A		

SECTION 4 - FIRE & EXPLOSION DATA

Flash Point	N/A	Method Used	N/A	Flammable Limits in Air % by Volume	N/A	LEL Lower	N/A	UEL Upper	N/A
Auto-Ignition Temperature	Above 600°F	Extinguisher Media	CO , dry chemical, foam, water spray						
Special Fire Fighting Procedures	Self contained breathing apparatus and protective clothing should be worn in fighting fires involving chemicals								

Unusual Fire and Explosion Hazards
Toxic fluorine gases are byproducts of combustion

SECTION 5 - PHYSICAL HAZARDS (REACTIVITY DATA)

Tribolube-26N

Stability Unstable Conditions to Avoid Strong Oxidizers
Stable

Incompatibility (Materials to Avoid) Oxidizing material can cause a reaction

Hazardous Decomposition Products Fluorine products, CO₂, traces of incompletely burned carbon.

Hazardous polymerization May Occur Conditions to Avoid None Known
Will Not Occur

SECTION 6 - HEALTH HAZARDS

1. Acute None 2. Chronic None

Signs and Symptom of Exposure Prolonged and repeated contact with skin may cause skin irritation

Medical Condition Generally Aggravated by Exposure No known medical condition that might be aggravated by exposure

Chemical Listed as Carcinogen or Potential Carcinogen National Toxicology Program Yes No I.A.R.C. Monographs Yes No OSHA Yes No

Emergency and First Aid Procedures Skin contact: Wipe off and wash with soap and water.

ROUTES OF ENTRY

1. Inhalation Remove to fresh air, if necessary seek medical attention
2. Eyes Flush with water, get medical attention
3. Skin Wipe off and wash with soap and water
4. Ingestion No known adverse effects are known, consult physician

SECTION 7 - SPECIAL PRECAUTION AND SPILL/LEAK PROCEDURES

Precautions to be Taken in Handling and Storage Use reasonable care. Do not store above 250°F or near flammables

Other Precautions Toxic vapors may evolve above 550°F; provide adequate ventilation if used above this temperature

Avoid spills; causes slippery surfaces

Steps to be Taken in Case Material is Released or Spilled Scrap up with proper tools; wipe up with absorbant cloth or paper towel; apply non-skid absorbant material to floor. Collect waste materials for salvage or disposal

Waste Disposal Methods (Consult federal, state, and local regulations) Dispose of in accordance with current Federal, State, and Local Regulations

SECTION 8 - SPECIAL PROTECTION INFORMATION/CONTROL MEASURES

Respiratory Protection (Specify Type) Not required unless product is being used as a mist

Ventilation Local Exhaust Not required Mechanical (General) Recommended Special Other

Protective Gloves Plastic disposable Eye Protection Safety glasses recommended

Other Protective Clothing or Equipment Plastic apron, fabric laboratory coat recommended

Work/Hygienic Practices Do not contaminate smoking materials; wash hands and / or contaminated area after exposure